



Collider-Accelerator Department

Safety Assessment Document

Linac, Tandem Van De Graaff, Booster, AGS, RHIC,
Transfer Lines and Experimental Areas

Revision 2

August 2004

Brookhaven National Laboratory

Editors:

R. Karol
E. Lessard
D. Passarello
J. Scott

Safety Assessment Document

Linac, Tandem Van De Graaff, Booster, AGS, RHIC, Transfer Lines and Experimental Areas

Contributors:

J. Alessi
D. Beavis
K. Brown
J. de Boer
C. Carlson
P. Cirnigliaro
A. Etkin
J. W. Glenn
C. Gardner
R. Grandinetti
H. C. Hseuh
P. Ingrassia
R. Karol
J. Levesque
E. Lessard
Y. Makdisi
J. Maraviglia
W. Meng
T. Nehring
A. Nicoletti
D. Passarello
C. Pearson
A. Pendzick
P. Pile
T. Roser
A. Rusek
J. Sandberg
J. Scott
J. Tuozzolo
M. Van Essendelft
N. Williams

Safety Assessment Document

Linac, Tandem Van De Graaff, Booster, AGS, RHIC, Transfer Lines and Experimental Areas

Approval Signatures:

Edward T Lessard

E. Lessard, Collider-Accelerator Department Associate Chair for ESHQ

David Lowenstein

D. Lowenstein, Collider-Accelerator Department Chair

Thomas BW Kirk Aug 25, 2004

T. Kirk, HENP Associate Laboratory Director

Michael Bebon 8/27/04

M. Bebon, Deputy Laboratory Director for Operations

Safety Assessment Document

Linac, Tandem Van De Graaff, Booster, AGS, RHIC, Transfer Lines and Experimental Areas

4. Chapter Four

4.1. Introduction	3
4.2. Hazard Analysis Approach.....	3
4.3. General Approach to Risk Minimization	6
4.4. Risk Minimization Approach for Radiation Hazards.....	8
4.5. Hazard Identification and Hazard Analysis.....	9
4.5.1. Conventional and Environmental Hazards.....	9
4.5.2. Radiation Hazards	14
4.5.3. Source Terms and Calculated Radiation Fields	17
4.5.3.1. Primary Beam.....	18
4.5.3.2. Prompt Secondary Radiation in Areas Outside Primary Beam Shielding	19
4.5.3.3. Induced Residual Activity	58
4.5.3.4. Activated Cooling Water.....	65
4.5.3.5. Soil Activation and Groundwater Contamination	71
4.5.3.6. Activated Air	72
4.5.3.7. Skyshine	76
4.5.4. Oxygen Deficiency Hazards.....	92
4.5.5. Electrical Hazards.....	101
4.5.6. Fire Hazards	103
4.5.7. Hazard Controls.....	105
4.5.8. Significant Environmental Aspects and Impacts.....	118
4.5.9. Hazard Reduction Associated With Waste Generation and Handling	121
4.5.10. Fire Detection, Egress, Suppression and Response	122
4.5.11. Routine Credible Failures	123
4.5.12. Maximum Credible Accidents	125
4.5.13. Risk Assessment to Workers, the Public and the Environment.....	131
4.5.14. Professional Judgment Issues	136
4.5.15. Methods Used in Evaluation of Radiological Hazards	137

5. Chapter Five

5.1 Background	1
5.2 Summary of ASE Content	6

6. Chapter Six

6. Chapter Six, Quality Assurance.....	1
6.1. Program.....	1
6.2. Personnel Training and Qualifications.....	3

Safety Assessment Document

Linac, Tandem Van De Graaff, Booster, AGS, RHIC, Transfer Lines and Experimental Areas

6.3. Quality Improvement	3
6.4. Documents and Records	4
6.5. Work Process	5
6.6. Design	6
6.7. Procurement	7
6.8. Inspection and Acceptance Testing	7
6.9. Management Assessment.....	8
6.10. Independent Assessment.....	9

7. Chapter Seven

7. Chapter Seven, Decommissioning and Decontamination Plan.....	1
7.1. Introduction.....	1
7.2. Baseline Conditions	3
7.3. End Point Goals	5
7.4. Regulatory Requirements.....	6
7.5. Decommissioning Methods	6
7.6. Waste Streams.....	7

8. Chapter Eight

8.1 References.....	1
8.2 Acronyms.....	14
8.3 Units.....	21

List of Figures and Tables

1. Chapter One

Figure 1.2.a Accelerators and the Collider within C-AD Site	4
Figure 1.2.b Collective Dose Equivalent Experience and Annual Proton History	8
Figure 1.2.5 Accelerators and the Collider Showing the Yellow and Blue Rings.....	13

3. Chapter Three

Figure 3.1 Site Overview	6
Figure 3.1.1.a Schematic of Collider-Accelerator Complex.....	13
Figure 3.1.1.b Tandem Van De Graaff Accelerators	14

Safety Assessment Document

Linac, Tandem Van De Graaff, Booster, AGS, RHIC, Transfer Lines and Experimental Areas

Table 4.5.3.s Annual-Activity Concentration Averaged over Target Room Volume And Annual Production Rate of Air Activation Products	74
Table 4.5.3.t Number of Neutrons Emitted from the Top of the Booster which Produce 5 mrem at the Site Boundary and 25 mrem at other Uncontrolled Areas or Non-C-AD Facilities.....	78
Table 4.5.3.u Total Annual Areal Dose Goal (rem-cm ²)	79
Table 4.5.3.v Flux Loss and Sky Shine Exposure Summary.....	81
Table 4.5.3.w Number of Neutrons Emitted from the Top of D, A, B or C Lines Which Produce 5 mrem at the Site Boundary and 25 mrem at Other Uncontrolled and Fully Occupied Locations	85
Table 4.5.3.x Neutrons Per Unit Area Per Unit Dose Equivalent at the Surface of a Thick Shield for the Condition of 28.5 GeV Protons Incident on a Target Behind the Lateral Shield and Total Annual Areal Dose Equivalent Goal (rem-cm).....	86
Table 4.5.3.y Dose Equivalent Rate at the Surface of a Lateral Shield from 28.5 GeV Protons for Different Overlying Materials.....	88
Table 4.5.3.z Lateral Shield Thickness Versus Surface Dose Equivalent Rate and Areal Dose Equivalent for 2.4×10^{20} Protons in an AGS Beam Line (Sect. 4.1.1)	89
Figure 4.5.4.a. Graph of the Fatality Factor (logarithmic scale) versus the Computed Oxygen Partial Pressure.....	95
Table 4.5.4.a - ODH Classification for Collider Buildings	100
Figure 4.5.13.a Range of Radiation Worker Dose at C-A Department for CY2000	132
Figure 4.5.13.b Decline in Radiation Worker Dose at C-A Department	132